

Mid-Model Update

Product Enhancements



RAME

VACTOR



COMMITMENT TO INNOVATION

After a few years of production of the Ramjet, we have continued to listen to our customers. We have implemented these improvements in this Ramjet mid-model update.




Control Panel

- Increased vertical distance from display to joystick
- Improved option integration
- Rodder pump switch to keypad
 - Option to double tap or long press
- New control box rotation
- New visor holding eliminating the need for the cam latch




-6"

2022 approx. 44" Extension





Reduced Front Bumper Extension

- Reduced projection of control box
- Reduced projection of reel from the front bumper
- Overall length reduction of 6" between control box and front projection resulting in overall vehicle length reduction.



User Preferences





NEW Service Intervals


how to set/reset them

Service Intervals	
Inspection Reset Reset	
Engine Oil Reset Reset	Hydraulic Oil R Rese






Winterization Reminder How to set / reset



Reduce Costs & Improve Time

Vactor Module Disconnect



Summary of Product Updates

New Features

Taller Control Box

- Improved Display Visor lid and lock
- More Controls on the Panel
- **Reduced Front Projection**
- Consolidated Electrical System
- Service Reminders
- Winterization Reminder
- Vactor Module Disconnect

Removed Features

Rear Bellypack Mounting Cradle on the Hose Reel



