



## ROVER X EVALUATION SERVICES

---

Let factory certified personnel at A&H Equipment Co. perform 21+ point evaluation on your ROVER X. Keep your unit working properly and at its peak performance with a 360° inspection over the cable reel/cable, crawler, camera, pendant, and wireless remote.

A&H Equipment will check for potential damage and will clean the camera, crawler, cables, and will replace the side plate O-rings and axle O-rings. We will make sure the pendant has the latest software update along with calibrating the screen and joysticks.

Cost of evaluation starting at \$899. Included in the evaluation you will receive a report on your unit after the evaluation has been completed, which includes an estimate for additional repair costs if needed.

If your repair exceed \$1000 or more, \$300 of the initial evaluation charge will be applied to the cost if A&H is chosen for the repairs.

-  Inspected by Factory Certified Personnel
-  360° Inspection on Entire Unit
-  21+ Point Inspection Available at A&H
-  Verify Latest Updates & Calibrations on Pendant
-  Evaluations starting at \$899



*Solutions You Trust Since 1963*

800.753.7566 [ahequipment.com](http://ahequipment.com)



## AREAS OF INSPECTION INCLUDE:

---

### Cable Reel/Cable

- Inspection for damage to cable reel/cable
- Inspect the laser sensors to make sure they are functioning properly
- Inspect connections of wires to ensure no damage
- Inspect the termination on the end of the cable
- Inspect the connector including the inside pins
- Inspect the guide rollers and ensure proper operation



### Crawler

- Inspect the seals and O-rings for leaks
- Inspect the drive motors and axles for wear and proper operation
- Inspect the cable and camera connectors on crawler
- Inspect rearview camera and back eye LED
- Replace side plate and drive axle O-rings



### Camera

- Inspect the seals and O-rings for leaks
- Inspect rotation shaft and roll function
- Inspect front window and LED function
- Inspect tilt axles and pitch function
- Inspect lasers and measurement function
- Replace tilt cover disk O-rings



### Pendant

- Verify the calibration of the screen and joysticks
- Verify proper recording and exporting of data
- Update to the latest version of software

### Wireless Remote

- Verify proper operation

